



Hurtman Rescue
Chief Judge: Cody Crose &
Jim Eberly
(Team Event)

Mean Time: 4 Minutes

Drop Dead Time: 6 Minutes

EVENT DESCRIPTION

Time starts at the judge's signal with lineworker standing at least an arm's length from 4x4 post in any direction. **Note:** The lineworker's belt and hooks will be hanging on the 4x4 post along with call script and radio. Rubber gloves will be inside the glove bag cuffs down and fingers up at the start of the event. If fingers protrude outside the bag the flap must be snapped. **Rubber gloves are required ground to ground.**

1. Scenario: You are at the jobsite, you have completed your JHA which has indicated that Reclosing is off and the remote SCADA controls have been switched from Supervisory to the Local position. With a NON-Reclosing Tag installed. A lineworker has climbed the pole and you suspect that he/she has made accidental contact with the bottom phase and is unresponsive.
2. Looking at the pole from the opposite side of the conductor, the hand line will be hung on the right side simulating an injury to a right-handed person. The hurtman will hang on an eye nut installed on the bottom bolt of the standoff arm on the conductor side of the pole. **NOTE:** A minimum of 1 ½ wraps around the pole is required with the handline.
3. 1st groundperson must check on the victim by hollering out "Are you okay" and designate someone to make the mayday call.
4. Scripted call must be made by 2nd groundperson.
Scripted Call:
"Mayday, Mayday. We have an accidental electrical contact at 1201 Schrock Road. Victim is unconscious. Rescue in progress. Send EMS."
5. Manikin should be tied under arms with three half hitches. Note: (eye splice should not be used as part of the hitches). The half hitch is the only acceptable knot. A 3"conduit will be used to measure tightness of knot.
6. Be sure to call out "headache" loudly when you drop your hand-line sheave. The sheave shall be dropped in the 5' circle radius at the base of the pole
7. A Bashlin belt 57-N will be used on the manikin. You must cut the Bashlin 57-A (Orange) insert. There will be a 10-point deduction for cutting the belt in the wrong place
8. Manikin must be lowered smoothly to the ground.
9. **Time will stop when Manikin is flat on the ground and slack in the handline.**
10. Lineworker must climb down the pole smoothly and safely. Note: There must be one gaff in the pole at all times when climbing down the pole. The fall arrest must remain attached for proper adjustment verification by the event judge.

11. The lineworker must use the hand-line provided.
12. Rubber gloves will be required for this event.
13. Deductions will be subtracted from 100, resulting in the final score.
14. Judging stops when the competitors Fall Restraint device has been checked for proper adjustment by the Event Judge and you are instructed to detach from the pole.

FIGURES

Figure A – paper drawing of event.

Figure B - Bashlin belt 57-N cut procedure.

MATERIALS PROVIDED:

1. Handline.

SPECIFICATION FIGURES

Specification Figure A – paper drawing of event.




Figure B

Specification Figure B - Bashlin belt 57-N cut procedure.

